

# domicile consulting

Property, Energy & Moisture Intrusion Inspections

PROTECTING YOUR PROPERTY INVESTMENT

## Inspection Report

Condominium Association

Property Address:

Chicago IL



Not The Real Building

Domicile Consulting

Dan Cullen IL Home Inspector License 450.000570 Expiration Date November 2012  
1033 W. Vernon Park Place Unit C  
Chicago IL 60607  
773-771-6466



## Table of Contents

[Cover Page](#)

[Table of Contents](#)

[Intro Page](#)

[I 4 POINT Inspection](#)

[Summary](#)

[Invoice](#)

[Agreement](#)

**Date:** 10/1/2011

**Time:** 09:00 AM

**Report ID:**

**Property:**

**Customer:**

**Real Estate Professional:**

Chicago IL

Condominium Association

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. purchasing this home. Any recommendations by the inspector to repair or replace sugg contractor. All costs associated with further inspection fees and repair or replacem purchase the property.

All comments by the inspector should be considered before ests a second opinion or further inspection by a qualified ent of item, component or unit should be considered before you

**Inspected (IN)** = I visually observed the item, component or unit and if no other comments were mad allowing for normal wear and tear.

e then it appeared to be functioning as intended

**Not Inspected (NI)** = I did not inspect this item, component or unit and made no representations of what will state a reason for not inspecting.

her or not it was functioning as intended and

**Not Present (NP)** = This item, component or unit is not in this home or building.

**Repair or Replace (RR)** = The item, component or unit is not functioning as intended or needs further inspe components or units that can be repaired to satisfactory condition may not need repl

ction by a qualified contractor. Items, acement.

**TYPE OF STRUCTURE:**

Low Rise Condominium  
Extra Info : Six Condominium Units

**APPROXIMATE AGE OF STRUCTURE:**

Under 10 Years

**STRUCTURE FACES:**

West

**CLIENT PRESENT?:**

Yes

**RADON TEST?:**

No

**WATER QUALITY TEST?:**

No

**WEATHER CONDITIONS:**

Clear

**AMBIENT TEMPERATURE:**

Below 60...A/C not operated due to risk of equipment damage.

**NUMBER OF STORIES:**

Three story, with Basement

**EXTERIOR WALL CONSTRUCTION:**

Masonry  
EXTERIOR WALL CLADDING MATERIAL : : Face  
Brick on West Facade. Jumbo Brick on North, East,  
and South Facades.

**FOUNDATION:**

Full basement (Finished coverings), Foundation Not  
Fully Visible  
FOUNDATION MATERIAL : : Poured Concrete

### I. 4 POINT Inspection

This report reflects the findings of a limited scope moisture intrusion investigation cause of the moisture intrusion that has become evident in several areas of the interior areas of the exterior wall assembly (wall cavities, wall framing, insulation, vapor retarders, etc.) could not be viewed. Bulk moisture can travel in unpredictable ways critically important to follow best construction practices regarding all exterior openings. This report is an attempt to compare the existing exterior wall and roof to the risk for ongoing moisture intrusion.

ion was to determine the location of the concealed moisture inside the space between the exterior wall cladding and the interior wall finishes. For these reasons, it is details so that the general risk for bulk moisture penetration into the wall assembly practices in the industry and to make recommendations for repairs that will reduce the risk for ongoing moisture intrusion.

ion was to determine the location of the concealed moisture inside the space between the exterior wall cladding and the interior wall finishes. For these reasons, it is details so that the general risk for bulk moisture penetration into the wall assembly practices in the industry and to make recommendations for repairs that will reduce the risk for ongoing moisture intrusion.

This home inspection is being conducted in accordance with the State of Illinois Home Inspector Licensing Act and following the American Society of Home Inspectors guide. This is a visual inspection of readily accessible systems and components of the home. The home inspector makes no guarantees regarding any of the home's systems or components. Only non-invasive practices may bring some defects to light that were not noted during your home inspection. If you discover any adverse conditions in the home after your Domicile Consultation, you will be refunded without question if you are unhappy with the inspection for any reason. No guarantees or warranties are provided in connection with the home inspection. Any disputes shall be resolved by the American Arbitration Association for a decision.

Inspector Licensing Act and following the American Society of Home Inspectors guide. This is a visual inspection of readily accessible systems and components of the home. The home inspector makes no guarantees regarding any of the home's systems or components. Only non-invasive practices may bring some defects to light that were not noted during your home inspection. If you discover any adverse conditions in the home after your Domicile Consultation, you will be refunded without question if you are unhappy with the inspection for any reason. No guarantees or warranties are provided in connection with the home inspection. Any disputes shall be resolved by the American Arbitration Association for a decision.

elms. No pest inspection. Some items. The inspection processes are used in the Basements and attics during inspection, please refer to the report provided for details that cannot be

#### ROOF COVERINGS:

Composition (Asphalt or Fiberglass) Shingles  
Modified Bitumen

Roofdeck decking prevented a full inspection of the roof covering.

#### ROOF VIEWED:

Roof Was Walked

#### Styles & Materials

#### Inspection Items

#### A. EXTERIOR WALLS, GROUNDS, CHIMNEYS, ETC.

Comments: Not Functioning or in need of repair




A. Picture 1 Front Exterior Stairs

(1) The joint between the poured concrete front steps and the adjacent masonry piers moisture and melting salts are not drawn into the masonry walls. Failure to provide make them subject to freeze/thaw damage. It is further recommended that the masonry then sealed using a high-quality silane or siloxane-based masonry water repellent in absorption of ice melting compounds which can result in ongoing and accelerating det units.

should be separated by a caulked capillary break so that such a break will result in saturation of the masonry piers and piers on either side of the concrete steps be cleaned and order to reduce the rate of moisture absorption as well as the deterioration of the Renaissance stone and the brick masonry



A. Picture 2 Aged and Deteriorated Caulking



A. Picture 3 Properly Tooled Sealant Joint With Backer Rod

(2) The application of the exterior sealants, a.k.a. caulking, was originally improper made for a near-term removal and replacement of the exterior sealant joints. In order absorb movement, and maintain durability high-quality materials inappropriate method

er and is now also deteriorating. It is recommended that plans be made for the sealant joints to prevent drafts, repel moisture, and s must be used. Please refer to the referenced article

regarding exterior sealants.

Caulking Basics



A. Picture 4 Limestone Mortar Joint

(3) The mortar joints at the corners of the stone window sills and between all lime a high-quality masonry caulking compound to reduce the risk of moisture saturation, masonry below the sill.

stone copings/sills should be raked out and sealed instead with moisture intrusion to the interior, and damage to the brick



A. Picture 5 Incomplete Movement Joint

(4) The masonry wall movement joints do not extend to the bottom of the foundation w the exterior wall movement joints by a qualified masonry restoration contractor is r feasible and advisable. No obvious cracking or signs of stress were noted at the low improper configuration.

all as is dictated by industry standards. Further review of ecommended in order to determine if completion of the joints is er termination of the incomplete movement joints despite their



A. Picture 6 Improperly Configured Wall Penetrations

(5) The openings in the masonry wall that allow the passage of the PVC vent piping a moisture intrusion. The openings are too large and are sealed with relatively brittle as urethane caulk. Further evaluation and repair of the PVC vent piping wall penetra recommended; ideally, the vent piping would pass through neatly cored brick masonry

re improperly configured and are therefore prone to allowing e cement mortar instead of a flexible and adhesive material such tions by a qualified masonry restoration contractor is units via openings that are slightly larger than the PVC

... piping themselves. This would allow the application of a properly configured sealant

joint.



A. Picture 7 Wanton and Willful Negligence

(6) A damaged brick was noted at the lower north exterior masonry wall which is a re-replaced by a qualified masonry contractor. The penetration through the individual brick "blow-out".

... suit of careless drilling. That individual brick should be replaced. Each masonry unit should be drilled carefully to prevent



A. Picture 8 Incomplete Sealant Joint

(7) The top edge of the steel deck ledgers should be properly sealed with high-quality sealant to prevent air entrapment and moisture intrusion through the through-wall ledger bolts.

... ty caulking compound in order to reduce the risk for moisture



A. Picture 9 Unsealed Air-Conditioning Refrigerant Line Penetration

(8) The exterior wall penetrations for the air-conditioning refrigerant lines and other utility lines should be sealed with urethane caulk or the equivalent in order to reduce the risk for drafts, energy loss




A. Picture 10 Feeder Conduit

... e electrical feeder conduits should be sealed using backer rod and sealant to prevent drafts, moisture intrusion, and pest entry into the structure.



A. Picture 11 Missing Flashing



A. Picture 12 Proper Flashing Detail



A. Picture 13 Substandard Cement Mortar

(9) The masonry wall flashings are either missing or improperly installed. The flash following locations: the top of the foundation wall; above the masonry pockets where below every window and door. Missing or improperly installed wall flashing can allow structural damage. The exterior masonry walls of this structure should be evaluated contractor.


Since retrofitting of missing or improperly installed masonry wall flashing is both association to deal with this issue on a case-by-case basis. If and when bulk moistu window openings then retrofitting of the missing flashings should be seriously consi

ings should protrude from the wall by at least 1/4" at the the floor joists are set into the concrete block; above and moisture to enter the home and cause rot, mold growth, and and repaired by a licensed and competent masonry

disruptive and expensive, it may be advisable for the condominium re intrusion becomes evident at the top or sides of the interior dered.



A. Picture 14 Mortar Gap



A. Picture 15 Re-Pointing Sequence

(10) The quality of the brick masonry mortar joints is substandard. Areas of the mortar are not properly tooled, improperly or inadequately applied cement mortar in a brick masonry masonry units and, after prolonged or wind driven rains, leads to bulk moisture intrusion into insulation, drywall, and wood framing. It is the inspector's opinion that the masonry joints and re-pointing. This process is expensive and is disruptive; however, it can be budgeted.

The application of clear masonry sealants is a poor substitute for properly configuring more masonry restoration contractors is recommended so that the condominium association

mortar joints appear to contain excessive amounts of sand and are not properly tooled. This mortar often leads to excess moisture saturation by the brick masonry units due to the moisture sensitive interior wall components like insulation, drywall, and wood framing. It is the inspector's opinion that the masonry joints and re-pointing. This process is expensive and is disruptive; however, it can be budgeted.

Further consultation with one or more masonry restoration contractors is recommended so that the condominium association can plan and budget for this process.



A. Picture 16 Rear Basement Entry Door

(11) Evidence of past moisture intrusion was noted at the rear basement exterior entry door. It is recommended that the cracked and loose mortar bed below the limestone sills be replaced by a qualified masonry restoration contractor. It is also recommended that the gap between the aluminum door threshold and the limestone sill be neatly and professionally sealed using the appropriate caulking compound.

It is recommended that the cracked and loose mortar bed below the limestone sills be replaced by a qualified masonry restoration contractor. It is also recommended that the gap between the aluminum door threshold and the limestone sill be neatly and professionally sealed using the appropriate caulking compound.




A. Picture 17 Improper Door Installation

(12) Exterior doors and windows in a masonry wall should be recessed approximately 1" from the weather. The exterior rear entry doors at the basement, first floor, and second-floor masonry wall. This puts them at much greater risk for moisture damage. It is recommended to trim the protruding door trim in order to protect from moisture intrusion and moisture damage.

The exterior rear entry doors at the basement, first floor, and second-floor masonry wall have been improperly installed and stand outboard of the weather. It is recommended that the aluminum flashing be installed over the top of the door frame.



A. Picture 18 Improper Limestone Coping And Flashing Details



A. Picture 19 Correctly Configured/Installed Coping



A. Picture 20 Caulk Smear

(13) A number of defects were noted in the masonry wall flashing details in the area of the limestone parapet capping.

The individual limestone blocks do not sufficiently overhang the concrete masonry units.

The drip groove at the outside edges of the stone is missing.

The cheap vinyl flashing (not approved for exposure to UV light) has been left exposed back flush to the wall and has resulted in gaps/openings that can easily allow both wind-driven rain and capillary suction to draw moisture into the masonry wall below the flashing.

The urethane sealant between the individual limestone blocks has been smeared over the surface.

The limestone parapet capping should be removed and reinstalled according to best practices and industry standards and is detailed in the attached Brick Industry Association's Technical Notes #7. Please refer specifically to Figure 18 for a comparison between the 'as built' details and the industry standard.



A. Picture 21 Improper Parapet Capping Detail

of the limestone parapet capping.

The individual limestone blocks do not sufficiently overhang the concrete masonry units and brick masonry units below.

The cheap vinyl flashing (not approved for exposure to UV light) has been left exposed back flush to the wall and has resulted in gaps/openings that can easily allow both wind-driven rain and capillary suction to draw moisture into the masonry wall below the flashing.

The urethane sealant between the individual limestone blocks has been smeared over the surface.


The limestone parapet capping should be removed and reinstalled according to best practices and industry standards and is detailed in the attached Brick Industry Association's Technical Notes #7. Please refer specifically to Figure 18 for a comparison between the 'as built' details and the industry standard.



A. Picture 22 Missing and Smeared  
Caulk at Scupper Opening



A. Picture 23 Loose Flap of Roofing Membrane At  
Scupper Opening



**NOTES:**

1. THIS DETAIL SHOULD BE USED ONLY WHEN THE ROOF DECK IS SUPPORTED BY THE WALL.
2. CONDUCTOR HEAD TO BE 1/4" MINIMUM BELOW BOTTOM OF THROUGH-WALL SCUPPER.
3. REFER TO THE ARCHITECTURAL SHEET METAL SECTION OF THE NRCA ROOFING AND WATERPROOFING MANUAL, FIFTH EDITION, FOR JOINERY AND SECUREMENT OPTIONS FOR SHEET METAL.
4. REFER TO THE BURME INTRODUCTION FOR ADDITIONAL INFORMATION.

A. Picture 24 Correct Scupper Configuration



A. Picture 25 Risk for Moisture Penetration at Scupper

(14) The design and the condition of the through-wall scuppers are inconsistent with membrane at the through-wall opening is prone to allowing moisture entrapment, moist smeared applications of caulking around the brick opening will not perform the intended function of moisture resistance. Each of the through-wall removal and replacement of the existing caulk/sealant joints or the eventual reconfiguration of the sheet-metal details

best practices and industry standards. The loose roof ure intrusion, and moisture damage. The successively ded function of moisture resistance. Each of the through-wall removal and replacement of the existing caulk/sealant joints or the eventual reconfiguration of the sheet-metal details



A. Picture 26 Improper Vinyl Siding Penetration



A. Picture 27 Vinyl Siding Mounting Blocks



A. Picture 28 Improper Vinyl Siding Penetrations



A. Picture 29 Installation of Vinyl Siding Mounting Blocks Recommended  
e pre-formed vinyl siding mounting blocks that are risk for moisture intrusion. They also allow the siding to amage, sealant failure, etc. Repair by a qualified siding

(15) It is recommended that all of the exterior wall penetrations be made through th manufactured for this purpose. The mounting blocks are self-flashing and reduce the expand and contract around the mounting block thereby reducing the risk for siding d specialist is recommended.



A. Picture 30 Projecting Soldier Course at Arch Top Window

(16) The projecting soldier courses of brick masonry on the exterior walls present a problem. The flat ledges at the top of the soldier courses result in increased moisture content. A masonry restoration contractor is recommended however, in the inspector's opinion, it is the inspector's opinion that the flat ledge at the masonry soldier courses should be repaired by the application of a cove of either mortar or caulk so that moisture is

not trapped. This presents an increased risk for moisture intrusion and moisture damage. Further evaluation by a qualified contractor is recommended. The flat ledge at the masonry soldier courses should be encouraged to flow away from these flat surfaces.



A. Picture 31 Loose Siding

(17) A number of defects were noted regarding the installation of the vinyl siding on the exterior wall cladding. Cement board siding, Kynar coated metal panels, or similar

materials are recommended over the penthouse walls. It is recommended that the contractor ensure the long-term moisture resistant performance of any weather resistant materials are recommended.



A. Picture 32 Mortar Cracking at Concrete Masonry Units Of the Inner Parapet

(18) It is recommended that the cracking at the mortar joints of the inner parapet be repaired by grinding out and re-pointing. These cracks appear due to moisture saturation and freeze/thaw cycling resulting from improper parapet capping details.

These cracks should be repaired by grinding out and re-pointing. These cracks appear due to moisture saturation and freeze/thaw cycling resulting from improper parapet capping details.

**B. ROOF COVERING, ROOF FLASHINGS, ROOF DRAINAGE.**

**Comments:** Not Functioning or in need of repair



B. Picture 1 "Deck of Card"


(1) The rooftop decks are supported by loose wooden blocks, many of which have become displaced. This creates a risk for damage to both the deck structure as well as to the roof covering. The deck will need to be completely reassembled by a qualified contractor in order to reduce the risk for ongoing damage. The deck frame would, ideally, be supported by opposing bearing walls and would not rest directly on the roof covering or roof surface. If space or budget constraints prevent such a support system then the deck bearing points should be lined up directly over and on top of the roof framing trusses below. This will prevent deflection and damage to the plywood roof sheathing. The roof membrane must be protected from keen edges and from heavy loads imposed upon small surface areas. Also, the deck framing should not block the prompt flow of roof run-off from reaching the gutters or scupper drains.

...e displaced. This creates a risk for damage to both the disassembled and reassembled by a qualified contractor in rted by opposing bearing walls and would not rest directly support system then the deck bearing points should be lined lection and damage to the plywood roof sheathing. The roof urface areas. Also, the deck framing should not block



B. Picture 2 Creates That Roofing Material

(2) Modified bitumen roofing membrane should not be creased at a 90° angle due to the risk for cracking, leaking, and damage. The use of cant strips at the roof to sidewall transition is required by both the roofing manufacturer as well as industry standards. It is recommended that the contractor. It is the inspectors opinion that the most cost-effective approach to reducing the risk for ongoing damage and leaking at these locations is to regularly monitor these creases and to apply additional roof coating as needed until the installation of a new roof covering becomes necessary.



B. Picture 3 Cant Strip at Roof Crease

...e risk for cracking, leaking, and damage. The use of cant er as well as industry standards. It is recommended that the ractor. It is the inspectors opinion that the most cost-effective o regularly monitor these creases and to apply additional roof



B. Picture 4 Risk for Damage to Roof Covering

(3) The installation of one or more sacrificial layers of roofing material is recommended at the rooftop. During hot weather, the modified bitumen roof material will so condensing unit, can result in scarring, damage and leaking of the roof covering.

ended underneath the rather keen edges of the air-conditioning fen and that, combined with the weight and vibration of the



B. Picture 5 Improper Shingle Application


(4) Multiple areas of improper roof shingle application were noted above the sloped and the shingle butt joints have been lined up over one another in multiple areas. T Since the existing composition shingle roof covering is at or near the end of its se than repair, be performed. Further evaluation by a qualified roofing contractor is r

cathedral ceilings at units 3S And 3N. The shingle rain guides these defects greatly increase the risk for leaking and damage. vice life, it is recommended that shingle replacement, rather ecommended.



B. Picture 6 Inappropriate Installation

(5) The aluminum breathers noted on this roof are not intended to serve as venting d free vent area and are incapable of venting the potentially large volumes of trapped ventilation of the roof plenum can result in condensation, mold growth, excess energy season. It is recommended that the existing undersized and inappropriate breathers b slope roof applications.



B. Picture 7 Low Slope Roof Vent

evices for the roof plenum. These devices have very little net heat and moisture inside the roof plenum. Inadequate y usage, and reduced indoor air comfort during the cooling e replaced with high-quality roof vents designed for low



B. Picture 8 Spongy Roof Sheathing

(6) Areas of apparently deteriorated roof sheathing were noted at the low slope roof further evaluated and repaired as needed in the course of the recommended roof cover



area between units 3N and 3S. These areas should be ing replacement.



B. Picture 9 Unsealed Roof Membrane



B. Picture 10 Improperly Detailed Edge Metal Flashing



B. Picture 11 Proper Edge Metal Flashing Detail

(7) A number of defects were noted at the modified bitumen roof covering over the up modified bitumen roof covering at the gutter edge greatly increases the risk for moisture damage. The metal flashing is not approved for this use and is not properly installed. It is recommended that this roof covering be repaired as soon as possible.

per levels of units 3N and 3S. The failure to seal the gutter edge greatly increases the risk for moisture damage from ice damming. The material used as edge flashing is not approved for this use and is not properly installed. It is recommended that this roof covering be repaired as soon as possible.



B. Picture 12 Loose Vent Pipe

(8) The PVC vent pipe at the Southeast corner of Unit 3N's rooftop deck is loose and recommended that the PVC piping penetration through the roof covering be evaluated a

therefore at risk for allowing moisture intrusion. It is nd repaired as needed by a qualified roofing contractor.


**C. ELECTRICAL SYSTEM, GROUNDING, CONNECTED DEVICES AND FIXTURES**

**Comments:** Not Functioning or in need of repair



C. Picture 1 Improper Electrical Connection

The connection between the driven ground rod and the grounding electrode conductor a grounding electrode conductor should be secured by the screw terminal and should not qualified electrician is recommended in order to help ensure the safe and effective



C. Picture 2 Correct Way to Secure Grounding Electrode Conductor

t the rear basement is improper and unsafe. The be squeezed between the clamp and the rod. Repair by a bonding and grounding of the electrical system.

**D. INSULATION, VENTILATION, ATTICS, ETC.**

**Comments:** Not Functioning or in need of repair



D. Picture 1 Mold-like Substances on Underside of Roof Sheathing

Mold-like substances were noted on surface/s of this home. Mold growth results from moisture problem. The source of the moisture that is the proximal cause of the mold-remediation is performed. Initial remediative steps may be advisable in order to red mycotoxins during the moisture investigation and repair process. Small areas of mold homeowner successfully. An EPA approved mildewcide with residual mold inhibiting pro improvement stores. Relatively non-porous surfaces such as tile, laminate, concrete, kept dry. Semi-porous surfaces such as wood framing and sheathing can also be cleane material significantly. Porous surfaces such as paper-faced gypsum drywall, cellulose

moisture on organic strata and is first and foremost a growth should be found and eliminated before final ue the release of mold spores, fungal fragments, and (10 square feet or less) can be remediated by the perties (Concrobium Brand) can be found at major home etc. should be surface cleaned with this type of product and d in this manner if fungal growth hasn't degraded the e insulation, etc. should be removed and replaced.

Air sampling and bulk sampling for mold is typically not required for successful rem identify possible mold contamination problems before remediation, it is usually unne

ediation. For routine assessments in which the goal is to cessary to collect and analyze air or settled dust samples for

mold analysis because decisions about appropriate intervention strategies can typically be made on the basis of a visual inspection. Also, sampling and analysis costs can be relatively high and the interpretation of results is not straightforward. Air and dust monitoring may, however, be necessary in certain situations, including 1) if an individual has been diagnosed with a disease associated with fungal exposure through inhalation, 2) if it is suspected that the ventilation systems are contaminated, or 3) if the presence of mold is suspected but cannot be identified by a visual inspection or bulk sampling.

lly be made on the basis of a visual inspection. Also, is not straightforward. Air and dust monitoring may, however, with a disease associated with fungal exposure through 3) if the presence of mold is suspected but cannot be identified by

**E. INTERIORS AND FINISHES**

**Comments:** Not Functioning or in need of repair



E. Picture 1 Round Top Window

(1) The drywall at the round top interior window returns has been applied directly over the masonry structure. This presents a strong risk for condensation, moisture damage, and mold growth. It is recommended that the drywall finishes at the round top window returns be removed, that all gaps in the arched rough masonry opening be sealed, and that the interior window returns be finished with a non-moisture sensitive material. The use of paper faced or paper backed drywall is not recommended at these locations common drywall. The use of non-paper faced gypsum wall board is recommended.

ver the masonry structure. This presents a strong risk for finishes at the round top window returns be removed, that returns be finished with a non-moisture sensitive material. . Green Board is only marginally more mold resistant than


[Fiberglass Faced Gypsum Wallboard](#)




E. Picture 2 Cathedral ceiling at Unit 3N



E. Picture 3 Mold Growth at Underside of Roof Sheathing



E. Picture 4 Improper Insulation



E. Picture 5 Faulty Insulation/Ventilation at Cathedral Ceiling Diagram

(2) The cathedral ceilings at units 3N and 3S are not properly ventilated and are p etc. The individual framing channels across the cathedral ceiling are lacking adequ This omission results in air stagnation and excess contact time between warm and moi roof sheathing during the heating season.

Also, the type of roof ridge vent used at this location is prone to allowing wind d repeated deterioration of the drywall tape at the peak of the cathedral ceiling is e

Also, the fiberglass batt insulation at the cathedral ceiling rafter channels is not and moisture above the insulation layer.

These construction defects have combined to create high moisture conditions conduciv the inspectors opinion that the most cost-effective (both in the long-term and short damage at the cathedral ceilings is to remove the existing drywall at the slopes of the continuous ridge vent and perform the required roof patching; apply open cell po roof decking and between the individual cathedral ceiling roof rafters; and to insta

The question of mold remediation should be considered in consultation with the insu once the drywall has been removed and the full extent of any mold growth can be dete

Care will be required at the ceiling can lights in order to prevent air leakage int surface ignition of combustible materials.

All of the recommendations for repairs or alterations that are contained in this rep specialty. It is recommended that the repairs/alterations be completed prior to clos buyer/renter with all appropriate documentation regarding the materials and methods at [www.angieslist.com](http://www.angieslist.com)

Prepared Using HomeGauge

<http://www.HomeGauge.com>

: Licensed To Domicile Consulting

rone to recurring condensation events, mold growth, wood rot, ate air intake openings at the lower termination of the rafters. st interior air leakage and the cold underside of the OSB

riven rain to enter the framing voids of the cathedral ceiling. The vidence of this process taking place.

been properly installed and is prone to allowing excess warmth

e to mold growth within the individual rafter channels. It is -term) approach to repairing the defects and remediating the the cathedral ceilings; remove the fiberglass insulation; remove lyurethane spray foam insulation against the underside of the ll a new drywall ceiling finish.

lation contractor and a qualified indoor air quality specialist rmined.

o the framing cavity and to also prevent any possibility for hot

ort should be performed by licensed and competent contractors with expertise in the ing. The contractor/s who perform the recommended repairs at the seller's direction used in the work. A list of contractors who have been rated and recommended by consu

appropriate trade or should provide the mers can be found

## Summary



### PROTECTING YOUR PROPERTY INVESTMENT

Domicile Consulting

1033 W. Vernon Park Place Unit C  
Chicago IL 60607  
773-771-6466

Customer  
Condominium Association

Address  
2468 Moldy Row  
Chicago IL

The following items or discoveries indicate that these systems or components do not dwell, or appear to warrant further investigation by a specialist, or require recommendations for routine upkeep of a system or component to keep it in proper function, efficiency, or safety of the home. This Summary is not the entire report of concern to the customer. It is recommended that the customer read the complete report.

function as intended or adversely affects the habitability of the dwelling. This summary shall not contain recommendations to upgrade or enhance the property. The complete report may include additional information of the property.

#### I. 4 POINT Inspection

##### General Summary

###### EXTERIOR WALLS, GROUNDS, CHIMNEYS, ETC.

###### Not Functioning or in need of repair

- (1) The joint between the poured concrete front steps and the adjacent masonry piers moisture and melting salts are not drawn into the masonry walls. Failure to provide make them subject to freeze/thaw damage. It is further recommended that the masonry and then sealed using a high-quality silane or siloxane-based masonry water repellent as the absorption of ice melting compounds which can result in ongoing and accelerated masonry units.
- (2) The application of the exterior sealants, a.k.a. caulking, was originally improper be made for a near-term removal and replacement of the exterior sealant joints. In order to absorb movement, and maintain durability high-quality materials inappropriate method regarding exterior sealants.

###### [Caulking Basics](#)

- (3) The mortar joints at the corners of the stone window sills and between all lime with a high-quality masonry caulking compound to reduce the risk of moisture saturation brick masonry below the sill.
- (4) The masonry wall movement joints do not extend to the bottom of the foundation w the exterior wall movement joints by a qualified masonry restoration contractor is r is feasible and advisable. No obvious cracking or signs of stress were noted at the

should be separated by a caulked capillary break so that such a break will result in saturation of the masonry piers and piers on either side of the concrete steps be cleaned t in order to reduce the rate of moisture absorption as well ing deterioration of the Renaissance stone and the brick

er and is now also deteriorating. It is recommended that plans rder for the sealant joints to prevent drafts, repel moisture, s must be used. Please refer to the referenced article

stone copings/sills should be raked out and sealed instead ion, moisture intrusion to the interior, and damage to the

all as is dictated by industry standards. Further review of ecommended in order to determine if completion of the joints lower termination of the incomplete movement joints despite

their improper configuration.

5. (5) The openings in the masonry wall that allow the passage of the PVC vent piping are allowing moisture intrusion. The openings are too large and are sealed with relative material such as urethane caulk. Further evaluation and repair of the PVC vent pipin contractor is recommended; ideally, the vent piping would pass through neatly cored the PVC piping themselves. This would allow the application of a properly configured
6. (6) A damaged brick was noted at the lower north exterior masonry wall which is a replaced by a qualified masonry contractor. The penetration through the individual b 'blow-out'.
7. (7) The top edge of the steel deck ledgers should be properly sealed with high-quali entrapment and moisture intrusion through the through-wall ledger bolts.
8. (8) The exterior wall penetrations for the air-conditioning refrigerant lines and th and urethane caulk or the equivalent in order to reduce the risk for drafts, energy
9. (9) The masonry wall flashings are either missing or improperly installed. The flash following locations: the top of the foundation wall; above the masonry pockets where below every window and door. Missing or improperly installed wall flashing can allow and structural damage. The exterior masonry walls of this structure should be evalua contractor.

Since retrofitting of missing or improperly installed masonry wall flashing is both condominium association to deal with this issue on a case-by-case basis. If and when of the interior window openings then retrofitting of the missing flashings should be

10. (10) The quality of the brick masonry mortar joints is substandard. Areas of the mor properly tooled; improperly or inadequately applied cement mortar in a brick masonry masonry units and, after prolonged or wind driven rains, leads to bulk moisture intr insulation, drywall, and wood framing. It is the inspector's opinion that the mason joints and re-pointing. This process is expensive and is disruptive; however, it can easier budgeting.

The application of clear masonry sealants is a poor substitute for properly configur more masonry restoration contractors is recommended so that the condominium associat

11. (11) Evidence of past moisture intrusion was noted at the rear basement exterior ent mortar bed below the limestone sills be replaced by a qualified masonry restoration aluminum door threshold and the limestone sill be neatly and professionally sealed
12. (12) Exterior doors and windows in a masonry wall should be recessed approximately 1 the weather. The exterior rear entry doors at the basement, first floor, and second- the masonry wall. This puts them at much greater risk for moisture damage. It is rec top of the protruding door trim in order to protect from moisture intrusion and mois
13. (13) A number of defects were noted in the masonry wall flashing details in the area

The individual limestone blocks do not sufficiently overhang the concrete masonry un

The drip groove at the outside edges of the stone is missing.

The cheap vinyl flashing (not approved for exposure to UV light) has been left expos cut back flush to the wall and has resulted in gaps/openings that can easily allow b the masonry wall below the flashing.

The urethane sealant between the individual limestone blocks has been smeared over

The limestone parapet capping should be removed and reinstalled according to best p attached Brick Industry Association's Technical Notes #7. Please refer specifically and the industry standard.

14. (14) The design and the condition of the through-wall scuppers are inconsistent with membrane at the through-wall opening is prone to allowing moisture entrapment, moist smeared applications of caulking around the brick opening will not perform the inten scuppers should be repaired by a qualified roofing contractor. Repair should include and securing of all roof membranes in and around the scupper. Plans should be made f around the through-wall scuppers by a qualified contractor.
15. (15) It is recommended that all of the exterior wall penetrations be made through th manufactured for this purpose. The mounting blocks are self-flashing and reduce the expand and contract around the mounting block thereby reducing the risk for siding c specialist is recommended.
16. (16) The projecting soldier courses of brick masonry on the exterior walls present a The flat ledges at the top of the soldier courses result in increased moisture conta masonry restoration contractor is recommended however, it is the inspectors opinion repaired by the application of a cove of either mortar or caulk so that moisture is

re improperly configured and are therefore prone to ly brittle cement mortar instead of a flexible and adhesive g wall penetrations by a qualified masonry restoration brick masonry units via openings that are slightly larger than sealant joint.

sult of careless drilling. That individual brick should be rick masonry unit should be drilled carefully to prevent

ty caulking compound in order to reduce the risk for moisture

e electrical feeder conduits should be sealed using backer rod losses, moisture intrusion, and pest entry into the structure.

ings should protrude from the wall by at least 1/4" at the the floor joists are set into the concrete block; above and moisture to enter the home and cause rot, mold growth, ted and repaired by a licensed and competent masonry

disruptive and expensive, it may be advisable for the bulk moisture intrusion becomes evident at the top or sides seriously considered.

tar appear to contain excessive amounts of sand and are not wall often leads to excess moisture saturation by the brick usion to the moisture sensitive interior wall components like ry walls would benefit greatly from grinding out of the mortar be performed on a wall by wall basis in order to allow for

ed and tooled mortar joints. Further consultation with one rion can plan and budget for this process.

ry doors. It is recommended that the cracked and loose contractor. It is also recommended that the gap between the using the appropriate caulking compound.

.5" to 2" in order to protect the wood components from floor have been improperly installed and stand outboard of ommended that the aluminum flashing be installed over the ture damage.

of the limestone parapet capping.

its and brick masonry units below.

ed at some locations. At other areas the flashing has been oth wind-driven rain and capillary suction to draw moisture into

cement mortar and will not perform as intended.

actices and industry standards and is detailed in the to Figure 18 for a comparison between the 'as built' details

best practices and industry standards. The loose roof ure intrusion, and moisture damage. The successively ded function of moisture resistance. Each of the through-wall removal and replacement of the existing caulk/sealant joints or the eventual reconfiguration of the sheet-metal details

e pre-formed vinyl siding mounting blocks that are risk for moisture intrusion. They also allow the siding to amage, sealant failure, etc. Repair by a qualified siding

n increased risk for moisture intrusion and moisture damage. ct time and reduced drainage. Further evaluation by a qualified that the flat ledge at the masonry soldier courses should be encouraged to flow away from these flat surfaces.

17. (17) A number of defects were noted regarding the installation of the vinyl siding on the condominium association plan for the replacement of the existing vinyl siding in order to the exterior wall cladding. Cement board siding, Kynar coated metal panels, or similar
18. (18) It is recommended that the cracking at the mortar joints of the inner parapet be repaired due to moisture saturation and freeze/thaw cycling resulting from improper parapet capping details.

#### ROOF COVERING, ROOF FLASHINGS, ROOF DRAINAGE.

##### Not Functioning or in need of repair

19. (1) The rooftop decks are supported by loose wooden blocks, many of which have become displaced. This creates a risk for damage to both the deck structure as well as to the roof covering. The deck will need to be completely disassembled and reassembled by a qualified contractor in order to reduce the risk for ongoing damage. The deck frame would, ideally, be supported by opposing bearing walls and would not rest directly on the roof covering or roof surface. If space or budget constraints prevent the use of such a support system then the deck bearing points should be lined up directly over and on top of the roof framing trusses below. This will prevent event deflection and damage to the plywood roof sheathing. The roof membrane must be protected from keen edges and from heavy loads imposed upon small surface areas. Also, the deck framing should not block the prompt flow of roof run-off from reaching the gutters or scupper drain s.
20. (2) Modified bitumen roofing membrane should not be creased at a 90° angle due to the use of cant strips at the roof to sidewall transition is required by both the roofing manufacturer er as well as industry standards. It is recommended that the creases at the roof to sidewall transitions be evaluated by a qualified roofing contractor. It is the inspectors opinion that the most cost-effective approach to reducing the risk for ongoing damage and leaking at these locations is to regularly monitor these creases and to apply additional roof coating as needed until the installation of a new roof covering becomes necessary.
21. (3) The installation of one or more sacrificial layers of roofing material is recommended underneath the rather keen edges of the air-conditioning bases at the rooftop. During hot weather, the modified bitumen roof material will so often and that, combined with the weight and vibration of the condensing unit, can result in scarring, damage and leaking of the roof covering.
22. (4) Multiple areas of improper roof shingle application were noted above the sloped cathedral ceilings at units 3S And 3N. The shingle rain guides and the shingle butt joints have been lined up over one another in multiple areas. These defects greatly increase the risk for leaking and damage. Since the existing composition shingle roof covering is at or near the end of its service life, it is recommended that shingle replacement, rather than repair, be performed. Further evaluation by a qualified roofing contractor is recommended.
23. (5) The aluminum breathers noted on this roof are not intended to serve as venting devices for the roof plenum. These devices have very little net free vent area and are incapable of venting the potentially large volumes of trapped heat and moisture inside the roof plenum. Inadequate ventilation of the roof plenum can result in condensation, mold growth, excess energy usage, and reduced indoor air comfort during the cooling season. It is recommended that the existing undersized and inappropriate breathers be replaced with high-quality roof vents designed for low slope roof applications.
24. (6) Areas of apparently deteriorated roof sheathing were noted at the low slope roof area between units 3N and 3S. These areas should be further evaluated and repaired as needed in the course of the recommended roof covering replacement.
25. (7) A number of defects were noted at the modified bitumen roof covering over the perimeter levels of units 3N and 3S. The failure to seal the gutter edge greatly increases the risk for moisture damage from ice damming. The material used as edge flashing is not approved for this use and is not properly installed. It is recommended that this roof covering be repaired as soon as possible and replaced as soon as practical.
26. (8) The PVC vent pipe at the Southeast corner of Unit 3N's rooftop deck is loose and therefore at risk for allowing moisture intrusion. It is recommended that the PVC piping penetration through the roof covering be evaluated and repaired as needed by a qualified roofing contractor.

#### ELECTRICAL SYSTEM, GROUNDING, CONNECTED DEVICES AND FIXTURES

##### Not Functioning or in need of repair

27. The connection between the driven ground rod and the grounding electrode conductor at the rear basement is improper and unsafe. The grounding electrode conductor should be secured by the screw terminal and should not be squeezed between the clamp and the rod. Repair by a qualified electrician is recommended in order to help ensure the safe and effective bonding and grounding of the electrical system.

#### INSULATION, VENTILATION, ATTICS, ETC.

##### Not Functioning or in need of repair

28. Mold-like substances were noted on surfaces of this home. Mold growth results from moisture on organic strata and is first and foremost a moisture problem. The source of the moisture that is the proximal cause of the mold-growth should be found and eliminated before final remediation is performed. Initial remediative steps may be advisable in order to reduce the release of mold spores, fungal fragments, and mycotoxins during the moisture investigation and repair process. Small areas of mold (10 square feet or less) can be remediated by the perties (Concrobium Brand) can be found at major home improvement stores. Relatively non-porous surfaces such as tile, laminate, concrete, etc. should be surface cleaned with this type of product and kept dry. Semi-porous surfaces such as wood framing and sheathing can also be cleaned in this manner if fungal growth hasn't degraded the material significantly. Porous surfaces such as paper-faced gypsum drywall, cellulose insulation, etc. should be removed and replaced.

Air sampling and bulk sampling for mold is typically not required for successful remediation. For routine assessments in which the goal is to identify possible mold contamination problems before remediation, it is usually unnecessary to collect and analyze air or settled dust samples for mold analysis because decisions about appropriate intervention strategies can typically be made on the basis of a visual inspection. Also, sampling and analysis costs can be relatively high and the interpretation of results is not straightforward. Air and dust monitoring may, however, be necessary in certain situations, including 1) if an individual has been diagnosed with a disease associated with fungal exposure through inhalation, 2) if it is suspected that the ventilation systems are contaminated, or 3) if the presence of mold is suspected but cannot be identified by a visual inspection or bulk sampling.

#### INTERIORS AND FINISHES

##### Not Functioning or in need of repair

29. (1) The drywall at the round top interior window returns has been applied directly over the masonry structure. This presents a strong risk for condensation, moisture damage, and mold growth. It is recommended that the drywall finishes at the round top window returns be removed, that all gaps in the arched rough masonry opening be sealed, and that the interior window returns be finished with a non-moisture sensitive material. The use of paper faced or paper backed drywall is not recommended at these locations. Green Board is only marginally more mold resistant than common drywall. The use of non-paper faced gypsum wall board is recommended.

#### Fiberglass Facet Gypsum Wallboard

30. (2) The cathedral ceilings at units 3N and 3S are not properly ventilated and are prone to recurring condensation events, mold growth, wood rot, etc. The individual framing channels across the cathedral ceiling are lacking adequate air intake openings at the lower termination of the rafters. This omission results in air stagnation and excess contact time between warm and moist interior air leakage and the cold underside of the OSB roof sheathing during the heating season.

Also, the type of roof ridge vent used at this location is prone to allowing wind driven rain to enter the framing voids of the cathedral ceiling. The repeated deterioration of the drywall tape at the peak of the cathedral ceiling is evidence of this process taking place.

Also, the fiberglass batt insulation at the cathedral ceiling rafter channels is not been properly installed and is prone to allowing excess warmth and moisture above the insulation layer.

These construction defects have combined to create high moisture conditions conducive to mold growth within the individual rafter channels. It is the inspectors opinion that the most cost-effective (both in the long-term and short-term) approach to repairing the defects and remediating the damage at the cathedral ceilings is to remove the existing drywall on the slopes of the cathedral ceilings; remove the fiberglass insulation; remove the continuous ridge vent and perform the required roof patching; apply open cell polyurethane spray foam insulation against the underside of the roof decking and between the individual cathedral ceiling roof rafters; and to install a new drywall ceiling finish.

The question of mold remediation should be considered in consultation with the insulation contractor and a qualified indoor air quality specialist once the drywall has been removed and the full extent of any mold growth can be determined.

Care will be required at the ceiling can lights in order to prevent air leakage into the framing cavity and to also prevent any possibility for hot surface ignition of combustible materials.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The suitability of the property for an specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

component or system; The causes of the need for a repair; The y specialized use; Compliance or non-compliance with codes, he property or its marketability; The advisability or inadvisability of e or absence of pests such as wood damaging organisms, installed. Home inspectors are not required to: Offer warranties stem or component; Enter any area or perform any procedure that their persons; Operate any system or component that is shut to normal operating controls; Disturb insulation, move that obstructs access or visibility; Determine the presence or absence ut not limited to mold, toxins, carcinogens, noise, contaminants m installed to control or remove suspected hazardous substances; this report is provided for the specific benefit of the customer(s), inspection to meet their specific needs and to obtain current

INVOICE



domicile consulting  
Property, Energy & Moisture Intrusion Inspections

PROTECTING YOUR PROPERTY INVESTMENT

Domicile Consulting  
1033 W. Vernon Park Place Unit C  
Chicago IL 60607  
773-771-6466  
Inspected By: Dan Cullen

Inspection Date: 10/1/2011  
Report ID:

**Customer Info:**  
Condominium Association

**Inspection Property:**  
2468 Moldy Row  
Chicago IL

**Customer's Real Estate Professional:**

**Inspection Fee:**

Service	Price	Amount	Sub-Total
Courtesy Inspection	1.00	1	1.00
			<b>Tax \$</b> 0.00
			<b>Total Price \$</b> 1.00

**Payment Method:** Net 30 Days  
**Payment Status:** Invoice Sent  
**Note:**

AGREEMENT

THIS IS A CONFIDENTIAL REPORT FOR THE CLIENTS NAMED HEREIN. THIS REPORT SUPERSEDES DISCUSSIONS AT OR PRIOR TO THE INSPECTION. THERE ARE NO GUARANTEES OR WARRANTIES IN THIS INSPECTION OR IN THE ACCOMPANYING REPORT.

ANY ORAL COMMENTS AND OTHER EXPRESSED OR IMPLIED

The purpose of this home inspection is to provide the client with a summary of the v regarding the portions of the premises which were in plain view and accessible at th responsible for hidden defects or for reporting on the condition of areas that are v major expenses and on safety issues. Some less important deficiencies may be discov building flaws is not provided.

usual observations which the inspector makes e time of the inspection. The inspector is not usually inaccessible. Emphasis is placed on ered, but an all-inclusive list of minor

This report is NOT a guarantee of code compliance of the building being inspected.

the advisability of the property for purchase.

This report is NOT a warranty of the condition of the premises, nor an opinion as to

This inspection is being conducted in accordance with the standards of practice of t the American Society of Home Inspectors, copies of which are available upon request this inspection: structural system/foundation; exterior; roof; plumbing; heating; co spaces; and fireplace components.

he Home Inspector License Act of Illinois and The following components are included in oling; electric; insulation and ventilation; interior

All inspection methods are non-invasive and only normal operating controls will be u switches, and lights will be tested for operation. Furniture, appliances, personal inspection.

sed. A representative number of outlets, items, stored materials, etc. are not moved for the

The inspector will walk on flat roofs where conditions permit, when they are safely potential exists for damage to the roof surface.

accessible with a 15' ladder, and where no

Central Air Conditioning units will not be operated unless the outside temperature h prior to the inspection; doing so could damage the air conditioning equipment.

as been above 60 degrees for at least 24 hours

Wet crawl spaces and those with either low headroom or insufficient openings are not the access area. Attics are entered when it is feasible and if there is sufficient

entered but are only visually examined from space to maneuver safely in the attic.

The inspector will not perform any procedures which could either lead to his/her per the subject property. This may result in some items or areas not

sonal injury or which could result in damage to being available for inspection.

Appliances and mechanical systems will be checked for proper operation during this i gas equipment, nor turn on any valves, nor re-set circuit breakers or fuses. The cl arranging for the maintenance of their mechanical equipment after closing. The clien be in use until closing and it is the client's responsibility to re-check all mechan within 24 hours prior to closing.

nspection. The inspector will not light any ients are responsible for maintaining or t should be aware that the equipment may still ical systems and appliances for proper operation

Domicile Consulting Inc. does not provide any engineering, architectural, pest contr connection with this home inspection unless otherwise agreed upon by both parties in

ol, or environmental inspection services in writing.

Domicile Consulting Inc. is not licensed for either asbestos or lead paint detection presence or absence of either material.

and makes no definitive representation as to the

All residential properties are subject to moisture related conditions that can cause perform testing for mold or fungi; makes no representations as to their definitive p specifically excludes them from this inspection unless otherwise agreed upon in writ

mold or fungi. Domicile Consulting Inc. does not resence or absence in this property; and ing by both parties.

The inspection of fireplaces is limited to the firebox and those portions of the flu required to light any gas appliances.

e that are readily viewable. The inspector is not

Many properties are being constructed with concrete block. A number of these struct problems as a result of improper materials and/or construction methods which may not inspection. Domicile Consulting Inc. makes no representation as to the performance specifically excludes them from this inspection except where otherwise indicated.

ures are experiencing water infiltration be readily determined from a visual of these construction assemblies and

Any verbal or written estimations or approximations made by the inspector regarding firm estimate nor a bid regarding such repair work. The purchaser must contact thei work to be done.

potential repairs of the premises are neither a r own agents regarding the actual price of any

It is understood and agreed that in the event of any error or omission on the part o

f Domicile Consulting Inc. in connection with this

inspection or this report, or in the event of any claim whatsoever against Domicile Consulting Inc., its employees, inspectors or agents shall be solely and exclusively inspection fee paid. Should a claim or dispute arise relating to the inspection or notified immediately in writing and shall be permitted to re-inspect the subject ite differing opinions of others nor shall any claim or dispute exist to items that have of those items by Domicile Consulting Inc. Any unresolved disputes shall be submit Chicago, Illinois, in accordance with the rules and regulations of the American Arbi agreement in this contract is a separate and independent covenant and agreement. If unenforceable, the remainder of the agreement remains valid and enforceable.

Consulting Inc., that any liability of Domicile limited to an amount no greater than the to the report, Domicile Consulting Inc. shall be m. Domicile Consulting Inc. shall not be liable for been repaired or modified prior to a re-inspection ed to and settled by binding arbitration only, in tration Association. Each covenant and any term or provision shall be invalid or

The undersigned agrees to pay \$ \_\_\_\_\_

1.00 \_\_\_\_\_ for this inspection.

SUBMITTED: \_\_\_\_\_ IL License#  
Domicile Consulting Inc.

050.000570  
Expires: 11/30/2006

THE UNDERSIGNED HAS READ AND AGREES WITH THE ABOVE AGREEMENT IN IT'S ENTIRETY:

ACCEPTED: \_\_\_\_\_ DATE: \_\_\_\_\_

ACCEPTED: \_\_\_\_\_ DATE: \_\_\_\_\_

**ILLINOIS HOME INSPECTOR ACT  
PROPERTY INSPECTION REPORT DISCLOSURE FORM**

Dear Client,

The Illinois Home Inspector License Act prohibits the inspector from disclosing client's written authorization. This includes but is not limited to casual conversa inspection as well as follow-up calls at a later date. Please take a moment to read sign at the bottom of the page.

any information \_\_\_\_\_ regarding the inspection without the tions or summations that may take place at the through the following options, initial your choice/s, and

Provide my Real Estate Agent or Broker with any necessary information regarding the

inspection.  Yes  No

Provide the Listing Agent or the Seller with any necessary information regarding the

inspection.  Yes  No

Provide my Attorney with any necessary information regarding this inspection.

Yes  No

Provide the Seller's Attorney with any necessary information regarding this inspecti

Yes  No

on.

Provide the following person/s with any necessary information regarding this inspect

ion.

\_\_\_\_\_  
\_\_\_\_\_

Signature: \_\_\_\_\_ Date \_\_\_\_\_